



# FINISH **FIRST** IN JOBSITE SAFETY!

Avoid jobsite utility damages & incidents!  
Use these **TEN TO WIN!**

Never excavate without a locate.

Submit locate requests in time, and with proper information.

Use white paint & white flags to mark excavation boundaries.

Do a pre-excavation jobsite walk-through inspection.

Photograph the jobsite, marks, and flags prior to excavation.

Protect the locate flags & marks from damage during excavation.

Honor the 2' tolerance zone around utilities.

Bore crews must never "blind bore" past utilities.

Hand dig safely and avoid damages caused by hand tools.

Vacuum excavation is the safest method for potholing.

Find more damage prevention information here

